## PART-II SCHOOL BUILDING SAFETY CERTIFICATE SEE SILLED BY S.D.E.OE. B.W.D. BAR DEBARTMEN

	(TO BE	FILLED B	Y S.D.E OF	P.W.D. B&I	R DEPARTMENT)
of the school:	NIDE	School		111maka	

1) This office Assistant Engineer/Junior Engineer visited the above mentioned School on and have visually inspected it for its safety and find it fil for normal use as a school building.

 In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.

3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging etc immediately of inspection of the undersigned be arranged to check the stability and the safety of the building.

4) This building is found visually safe hence it is expected that it can be safety occupied for normal use uo to (indicate year up to which it can be used ) 01.04.2024 to 31.03.2025.

Ref. No. 179

Dated 2015 24

Sub Divisional Engineer
Provl. Sub Division
PWD B & R Nakodar

